

386

BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,
PRINCIPAL BENCH, NEW DELHI

ORIGINAL APPLICATION NO. 94/2013

IN THE MATTER OF :

Vikrant Kumar Tongad

Applicant

Vs.

Delhi Metro Corporation & Others

Respondent

SL.	PARTICULARS	DOH 10.09.2014 PAGES
1.	Additional Status Report by D PCC	01 - 03
2.	<u>ANNEXURE-1</u> Copy of Public Notice dated 12.08.2014	04
3.	<u>ANNEXURE-2</u> Copy of the Office order dated 17.07.2014	05-06
4.	<u>ANNEXURE-3</u> Status Reports of 100 hospitals	07-13
5.	<u>ANNEXURE-4</u> Status of Inspection of Rainwater Harvesting System in Hospital's	14
6.	<u>ANNEXURE-5</u> Status of Rain Water Harvesting System. of RWA's	15-18

(Sanjeev Ralli and Aayush Juneja)
ADVOCATE
FOR THE RESPONDENT NO.2 &4
391, Lawyers Chamber Block-II,
Delhi High Court
NEW DELHI - 110002

New Delhi
Dated:09.09.2014

375 ①

BEFORE THE HON'BLE NATIONAL GREEN TRIBUNAL,
PRINCIPAL BENCH, NEW DELHI

ORIGINAL APPLICATION NO. 94/2013

IN THE MATTER OF :

Vikrant Kumar Tongad

Applicant

Vs.

Delhi Metro Rail Corporation Ltd.

Respondent

**ADDITIONAL COMPLIANCE AFFIDAVIT ON BEHALF OF GOVT. OF
NCT OF DELHI AND DELHI POLLUTION CONTROL COMMITTEE**

I, Arun Mishra, aged about 50 years, working as Additional Secretary (Environment) and Member Secretary, Delhi Pollution Control Committee, do hereby solemnly state as under :

1. I say that I am working as Additional Secretary (Environment) and Member Secretary, Delhi Pollution Control Committee and thus conversant with the relevant facts of the matter as per the official records.
2. I say that this Hon'ble Tribunal vide order dated 04.07.2014, directed as follows:

"The Committee so constituted shall examine these Replies, conduct a site visit to the premises of all the respective RWA's and submit the report to the Tribunal.

The Report shall specifically deal with what capacity of rain harvesting treatment devices need to be, if it is already in place whether they are operational and achieving targets expected of such devices and if not, the measures the RWA's are required to take."

3. I say that this Hon'ble Tribunal vide order dated 05.08.2014, directed as follows:

"We further direct all the Hospitals Private or Government to submit their Report to the DPCC who in return shall file the status report in regard to installation, functioning of RWH in these respective Hospitals."

4. That in compliance with the order dated 06.05.2014, following action was initiated by DPCC:

(a) 2206 letters were issued to Residents Welfare Associations in Delhi.

(b) Out of 2206, 157 Residents Welfare Associations filed reply to DPCC.

374 (2)

- (c) 196 letters out of 2206 issued to Residents Welfare Associations were returned back undelivered.
 - (d) Out of 2206, 22 Residents Welfare Associations mentioned in their reply that they are having Rain Water Harvesting System.
 - (e) DPCC issued letters to hospitals on 03.07.2014 which are having 100 beds or more, asking them to file status of Rain Water Harvesting System in their premises.
5. That in compliance with the orders dated 06.05.2014 & 04.07.2014, Department of Environment, Govt. of NCT of Delhi has issued a Public Notice in the daily newspapers of Delhi on 12.08.2014 (in English, Hindi, Punjabi, Urdu newspapers), inter-alia mentioning the orders of Hon'ble Tribunal and asking all Residents Welfare Associations, Hospitals and concerned authorities/agencies in the National Capital Territory of Delhi to file their replies on affidavit to the Committee constituted by Hon'ble National Green Tribunal and submit the replies to the office of DPCC within two weeks. Copy of the Public Notice is enclosed herewith as Annexure-1.
 6. That, as directed, Environment Department has constituted four Committees, consisting of members of CGWA, DJB and DPCC vide order Dated 17.07.2014. Copy of the order is enclosed herewith as Annexure-2.
 7. That, In compliance of Hon'ble Tribunal's order dated 05.08.2014, DPCC has again directed vide letters dated 21.08.2014 the hospitals having 100 beds or more to comply with the aforesaid directions of Hon'ble National Green Tribunal and submit their report to DPCC.
 8. That as on 08.09.2014, 84 affidavits/ replies have been received from the Hospitals. As per these replies, 68 hospitals have stated that they have installed Rain Water Harvesting Systems which are in functional condition and replies received from these 68 hospitals have been provided to the respective four committees to conduct inspections of their Rain Water Harvesting Systems. Further two hospitals namely M/s Safdurjung Hospital & V.M.M.C and M/s Jai Prakash Narayan ApexTrauma Centre were earlier found to have installed Rain Water Harvesting Systems. 14 Hospitals have not furnished any affidavit / reply till 08.09.2014 which are listed from S.No. 87 to 100 of status of 100 hospitals enclosed herewith as Annexure 3. Out of these 68 hospitals inspections have been carried out by respective Committees in case of 5 hospitals w.r.t the Rain

393
③

Water Harvesting Systems installed in these hospitals so as to know the status. Status of these Hospitals as on 08.09.2014 is enclosed herewith as

Annexure 4

9. That as on 08.09.2014, 22 no. of representations received from Residents Welfare Associations claiming the existence of Rain Water Harvesting Systems have been forwarded to the respective four committees constituted vide order dated 17.07.2014 to conduct inspections of Rain Water Harvesting Systems installed so as to know their status. Status of these Rain Water Harvesting Systems as on 08.09.2014 is enclosed herewith as

Annexure 5

Anam Moh
Deponent

Verification :

Verified on this 9th day of September, 2014 that the contents of the above affidavit are true and correct to my knowledge and nothing material has been concealed therefrom.

Anam Moh
Deponent

Government of National Capital Territory of Delhi
Department of Environment
6th Level, C-Wing, IP Estate New Delhi-110002

PUBLIC NOTICE

Dated:

Whereas the National Green Tribunal, Principal Bench, vide order dated the 6th, May 2014 and the 4th July 2014 in M.A. No. 808 of 2013 in original application no. 94 of 2013 in the matter of Vikrant Kumar Tongad Vs. Delhi Metro Rail Corporation has directed the Government of National Capital Territory of Delhi to issue notice to all hospitals and bodies and Residents Welfare Associations in the National Capital Territory of Delhi to state on affidavit as to whether the rain water harvesting system has been installed by them or not respectively and if installed whether it is functional or not;

And whereas vide order dated the 4th July 2014, the National Green Tribunal has constituted a Committee to examine the replies of RWAs etc and conduct a site visit to the premises of all the respective Resident Welfare Associations and submit a report to the National Green Tribunal on the next date of hearing.

Now, therefore all the Resident Welfare Associations, hospitals and concerned authorities/ agencies in the National Capital Territory of Delhi are hereby given Notice to file their replies on affidavit to the Committee constituted by the National Green Tribunal stating as under:-

- Whether Rain Water Harvesting System has been installed or not.
- If installed, number of such systems / pits, their capacity and whether they are functional or not. Catchment area, size of Recharge Pit, Dia & Depth of Injection Well, Condition of filter & design approving authority, etc. may also be mentioned.

The aforesaid replies be submitted in the office of Delhi Pollution Control Committee, (Kind Attn : Sh. D.K. Srivastava, EE), 4th Floor, ISBT Building, Kashmere Gate, New Delhi- 110006 within two weeks of this notice.

As per directions of National Green Tribunal, Committees for different Revenue districts of National Capital Territory of Delhi have been constituted to conduct site visits to the premises of all the respective Resident Welfare Associations.

Details are also available on website of DPCC
(www.dpcc.delhigovt.nic.in)

Sanjiv Kumar, IAS
Secretary (Environment)

DIP/0788/14-15

cum Chairman (Delhi Pollution Control Committee)

Department of Environment
Government of NCT of Delhi
 6th level, C-Wing, Delhi Secretariat
 I.P.Estate, New Delhi-110002
 Ph: 23392306

No 10(141)/(Env.)/2014 / 12145 - 12157

Dated: 17-7-2014

ORDER

In pursuant to the compliance of National Green Tribunal Order in M.A. No.808 of 2013 in Original Application No. 94 of 2013 Vikrant Kumar Tongad Vs Delhi Metro Rail Corporation Limited vide dated 4th July 2014 (copy of order enclosed), following four Committees are hereby constituted regarding functioning status of rainwater harvesting structures installed in the nine districts (as per earlier boundaries).

S.NO.	Committee	Names of Committee members	Districts
1.	Committee I	(a) Sh. V.P. Sharma, Superintending Engineer(South West), DJB (M: 9650291024) (b) Sh. N. Jyothi Kumar, Senior Hydrologist, CGWB (M: 9717449044)	South and South-West
2.	Committee II	(a) Sh. Ajay Gupta, Superintending Engineer (Central), DJB (M: 9650291023) (a) Sh. M. K. Garg, Scientist C, CGWB (M:9467211009)	North and North-West
3.	Committee III	(a) Sh. N.K.Tomar, Superintending Engineer(West), DJB (M: 8800094933) (b) Sh. V.K Jain, Environmental Engineer, DPCC (M:9717593533)	West, Central and New Delhi
4.	Committee IV	(b) Sh. Virender Kumar, Superintending Engineer (East), DJB (M: 9650290867) (c) Sh. N.K. Joshi, Environmental Engineer, DPCC (9717593527)	East and North-East

As per the directions of the Tribunal, the Committees shall examine these replies, conduct a site visit to the premises of all the respective RWA's and submit the report to the Tribunal. The Report shall specifically indicate with what capacity of rain harvesting treatment device need to be, if it is already in place whether they are operational and achieving targets expected of such devices and if not, the measures the RWA's are required to take.

The Committees will be coordinated by Officers of Department of Environment, GNCTD and Delhi Pollution Control Committee. Details of inspection sites be provided by Sh. K. Kumar, EE (DPCC) (Mobile: 9717593539) or can be downloaded from DPCC / Department of Environment official website (www.dpcc.delhigovt.nic.in/ / www.environment.delhigovt.nic.in).

(Sandeep Mishra)
Addl. Secretary (Env.)

Copy for kind information to:

- Sh. N. Jyothi Kumar, Senior Hydrologist, CGWB, 18/11, Jam Nagar House, India Gate, Man Singh Road, New Delhi-110001
- Sh. M. K. Garg, Scientist C, CGWB, 18/11, Jam Nagar House, India Gate, Man Singh Road, New Delhi-110001

370

(6)

3. Sh. N.K.Tomar, Superintending Engineer(West), Delhi Jal Board, Varunalaya Ph-II, Jhandewalan, Karol Bagh, New Delhi-110005.
4. Sh. Virender Kumar, Superintending Engineer (East), Delhi Jal Board, Varunalaya Ph-II, Jhandewalan, Karol Bagh, New Delhi-110005.
5. Sh. Ajay Gupta, Superintending Engineer (Central), Delhi Jal Board
6. Sh. V.P. Sharma, Superintending Engineer(South West), Delhi Jal Board
7. Sh. V.K Jain, Environmental Engineer, DPCC
8. Sh. N.K Joshi, Environmental Engineer, DPCC
9. Sh. K. Kumar, Environmental Engineer, DPCC
10. PS to Chairman, Central Ground Water Authority, West Block-II, Wing-3 Sector-1, R.K. Puram, New Delhi-66
11. PS to Secretary (Environment), GNCTD.
12. PS to CEO, Delhi Jal Board, Varunalaya Ph-II, Jhandewalan, Karol Bagh, New Delhi-110005.
13. PS to Member Secretary, DPCC, 4th & 5th Floor, ISBT Building Kashmere Gate, Delhi-06
14. PA to Director (Env.), GNCTD



(Sandeep Mishra)
Add. Secretary (Env.)

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd.". (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
1	Delhi Heart & Lung Institute	3-MM II, Panchkuian Road, New Delhi-55	Yes	Yes	
2	Action Cancer Hospital (A Unit of Manav Sevarth Trust)	H-2/FC-34, A-4, Paschim Vihar, New Delhi-63	Yes	Yes	
3	B.M. Gupta Hospital Pvt. Ltd.	H-11-15, Uttam Nagar, New Delhi-59	Yes	Yes	
4	Jeewan Nursing Home & Hospital	2-B, Pusa Road, New Delhi-05	Yes	Yes	
5	Jeewan Mala Hospital Pvt. Ltd.	67/1, New Rohtak Road, New Delhi-5	Yes	Yes	
6	RLKC Hospital Metro Heart Institute (A Unit of Dr. R.L.Khera Charitable Trust)	Naraina Road, Pandav Nagar, Opposite Shadipur Depot, Naraina Road, Delhi-08	Yes	Yes	
7	Brahm Shakti Hospital & Research Centre	U-1/78, Budh Vihar, Rohini, Delhi-110086	Yes	Yes	
8	Pushpawati Singhania Research Institute for Liver Renal and Digestive Diseases	Sheikh Sarai Phase-II, Press Enclave Marg, New Delhi-17	Yes	Yes	
9	Saroj Hospital	2, Institutional Area, Sec-14, Madhuban Chowk, Rohini, Delhi-85	Yes	Yes	
10	Nazar Kanwar Surana Hospital (A Unit of Bram Health Care Pvt. Ltd.)	219-220, N.K. Surana Marg, Gulabi Bagh, Delhi-07	Yes	Yes	
11	Madhukar Multispeciality Hospital and Research Centre	Plot No. 5, FC-29, Geetanjali Enclave, New Delhi	Yes	Yes	
12	Primus Ortho & Spine Hospital (Delhi Hospital Society)	2, Chandergupt Marg, Chankyapuri, New Delhi-21	Yes	Yes	
13	Shanti Mukund Hospital	2, Institutional Area Vikas Marg Extension, Delhi-92	Yes	Yes	
14	Indian Spinal Injuries Centre	Sector-C, Vasant Kunj, New Delhi-70	Yes	Yes	
15	Moolchand Kharaiti Ram Hospital & Ayurvedic Research Institute	Lajpat Nagar-III, New Delhi-24	Yes	Yes	
16	Sant Parmanand Hospital	18, Shamnath Marg, Civil Lines, Delhi-54	Yes	Yes	
17	Metro Hospital & Cancer Institute (Eariler Anand Hospital)	21, Community Centre, Preet Vihar, Delhi-92	Yes	Yes	
18	Fortis Lt. Rajan Dhall Charitable Trust	Sector- B, Pocket-1, Aruna Asaf Ali Road, Vasant Kunj, Delhi-70	Yes	Yes	

368
8

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd." . (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
19	Tirath Ram Shah Charitable Hospital	2 A, RBL, Ishwar Das Sawhney Marg, Rajpur Road, New Delhi-54	Yes	Yes	
20	Sunder Lal Jain Charitable Hospital	Ashok Vihar, Phase III, Delhi-52	Yes	Yes	
21	Institute of Liver & Biliary Sciences	D-1, Vasant Kunj, New Delhi	Yes	Yes	
22	Max Super Speciality Hospital	1, Press Enclave Road, Saket, New Delhi-17	Yes	Yes	
23	Fortis Hospital Ltd (Eariler Oscar Biotech Pvt Ltd.)	A-Block, Shalimar Bagh, Delhi- 88	Yes	Yes	
24	Dharamshila Cancer Hospital & Research Centre	Vasundhra Enclave, Delhi-96	Yes	Yes	
25	Shri Balaji Action Medical Institute Unit of Lala Munni Lal Mange Ram Charitable Trust Hospital	FC-34, A-4, Paschim Vihar, New Delhi-63	Yes	Yes	
26	Swami Dayanand Hospital	Shahadara, Delhi-32	Yes	Yes	
27	Central Jail Hospital	Tihar, New Delhi-64	Yes	Yes	
28	Rajiv Gandhi Cancer Institute & Research Centre	D-18, Sector-V, Rohini, New Delhi-85	Yes	Yes	
29	Holy Family Hospital	Okhla Road, New Delhi-25	Yes	Yes	
30	Sanjay Gandhi Memorial Hospital	Mangolpuri, Delhi-83	Yes	Yes	
31	Janakpuri Super Specility Hospital (Govt. of Delhi)	C-2/B, Janakpuri, New Delhi-58	Yes	Yes	
32	Batra Hospital & Medical Research Centre	1, Tughlakabad Institutional Area, Mehrauli Badarpur Road, New Delhi-62	Yes	Yes	
33	Dr. Baba Saheb Ambedkar Hospital	Sector-6, Rohini , New Delhi-85	Yes	Yes	
34	Indraprastha Medical Corporation Ltd. (Apollo Hospital Enterprises Ltd.)	Sarita Vihar, Mathura Road, New Delhi-76	Yes	Yes	
35	Deen Dayal Upadhya Hospital	Hari Nagar, New Delhi-64	Yes	Yes	
36	Sir Ganga Ram Hospital	Rajinder Nagar, New Delhi -60	Yes	Yes	
37	Guru Teg Bahadur Hospital	Dilshad garden, Shahdara, Delhi-32	Yes	Yes	
38	Lady Hardinge Medical College & Suchtra Kripalani & Kalawati Hospitals	Shaheed Bhagat Singh Marg, New Delhi-01	Yes	Yes	
39	All India Institue of Medical Science	Ansari Nagar, New Delhi-29	Yes	Yes	

367
9

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd." . (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
40	Rao Tula Ram Memorial Hospital	Jaffarpur, New Delhi-43	Yes	Yes	
41	Rockland Hospital	Sector-12, HAF-B, Phase-I, Dwarka, New Delhi-75	Yes	Yes	
42	Bhagwati Hospital (A unit of Sarvodaya Health Foundation (Regd.) Delhi)	CS/OCF-6, Sector-13, Rohini, Delhi-85	Yes	Yes	
43	Institute of Human Behaviour & Allied Sciences (IHBAS)	Dilshad Garden, Delhi-95	Yes	Yes	
44	Saket City Hospital (A unit of Gujarmal Modi Hospital & Research Centre for Medical Sciences)	Mandir Marg, Press Enclave Road, Saket, New Delhi-17	Yes	Yes	
45	Fortis Escorts Heart Institute & Research Centre	Okhla Road, New Delhi-25	Yes	Yes	
46	Dr. B.L. Kapur Memorial Hospital	Pusa Road, Delhi -05	Yes	Yes	
47	Nehru Homeopathic Medical College And Hospital	B-Block Defence Colony, New Delhi-24	Yes	Yes	
48	Lal Bahadur Shastri Hospital	Khichripur, Delhi-91	Yes	Yes	
49	Santom Hospital	D-5 & 6, Prashant Vihar, Rohini, New Delhi-85	Yes	Yes	
50	M.G.S Super Speciality Hospital	35/37, Rohtak Road, West Punjabi Bagh, Rohtak Road, New Delhi-26	Yes	Yes	
51	Bensups Hospital (B.R. Dhawan Memorial Charitable Trust)	Bensups Avenue, Near K.M. Chowk, Sector-12, Dwarka, New Delhi - 110075	Yes	Yes	
52	Max Super Speciality Hospital (A unit of Balaji Medical & Diagnostic Research Centre) (New Building, East Block)	108-A, Indraprastha Extention, Patparganj, New Delhi-92	Yes	Yes	
53	Max Super Speciality Hospital (A unit of Balaji Medical & Diagnostic Research Centre) (Old Building, West Block)	108-A, Indraprastha Extention, Patparganj, New Delhi-92	Yes	Yes	
54	ESI Hospital	Jhilmil, Delhi-95	Yes	Yes	

366

(1)

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd." . (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
55	Max Super Speciality Hospital (A unit of Max Health Care Institute Ltd.)	FC-50, C & D Block, Shalimar Bagh Delhi-88	Yes	Yes	
56	Max Super Speciality Hospital (East Block) (A unit of Devki Devi Foundation)	2, Press Enclave Road, Saket, New Delhi 110017	Yes	Yes	
57	HAH Centenary Hospital (Majeedia Hospital)	Jamia Hamdard, IHMMR Campus, Hamdard Nagar, New Delhi-62	Yes	Yes	
58	Maharaja Agrasen Hospital	West Punjabi Bagh, New Delhi-26	Yes	Yes	
59	National Institute of Tuberculosis & Respiratory Disease	Sri Aurbindo Marg, Near Qutub Minar, New Delhi-30	Yes	Yes	
60	Rajan Babu Institute for Pulmonary Medicine & Tuberculosis Hospital	GTB Nagar, Kingsway Camp, Delhi-9	Yes	Yes	
61	Rockland Hospital	B-33-34, Qutab Institutional Area, New Delhi-16	Yes	Yes	
62	Balaji Medical & Diagnostic Research centre	108-A, Indraprastha Extention, Patparganj, New Delhi-92	Yes	Yes	
63	A & U Tibbia College Hospital	Karol Bagh, New Delhi-5	Yes	Yes	
64	Kasturba Hospital	Near Jama Masjid, Darya Ganj, New Delhi-02	Yes	Yes	
65	City Hospital	B-1/1, N.E.A. Pusa Road, New Delhi-60	Yes	Yes	
66	Deepak Memorial Hospital	Karkardoma, 5, Institutional Area, Vikas Marg Extention-2, Delhi-92	Yes	Yes	
67	Kukreja Hospital & Heart Centre	C-1, Vishal Enclave, New Delhi-27	Yes	Yes	
68	Chacha Nehru Bal Chikatsaly (Geeta Colony Children Hospital)	Geeta Colony, Delhi-31	Yes	Yes	
69	Jai Prakash Narayan Apex Trauma Centre	Raj Nagar, AIIMS, New Delhi-29	-	YES	As per earlier record, status of RWHS is already submitted before Hon'ble NGT
70	Safdarjung Hospital & V.M.M.C.	Aurbindo Marg, New Delhi-29	-	Yes	As per earlier record, status of RWHS is already submitted before Hon'ble NGT

263
(11)

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd." . (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
71	Ram Manohar Lohia Hospital	Baba Kharak Singh Marg, New Delhi-01	Yes		Reply received that they have written a letter to EE, CPWD to provide information reg. RWHS installation. The reply does not reveal about installation of RWHS.
72	Northern Railway Central Hospital	Basant Lane, New Delhi-55	Yes		A letter dated 26.08.14 was written by Medical Director, Central Hospital to Div. Rly Manager wherein it is asked to comply with the NGT directions. The copy of letter marked to DPCC and letter does not reveal about installation of RWHS.
73	Aruna Asaf Ali Hospital	5 Rajpur Road, Delhi-54	Yes	No	Reply received on 08.09.14 stated that RWHS is not required due to high water table in Mansoon Seasons
74	Hindu Rao Hospital	Delhi-110007	Yes	No	Reply dated 08.09.2014 received that Estimate has been prepared for two locations & submitted for Budget allocation. In addition, One RWHS has been provided at entry of Hospital by Delhi Jal Board.
75	Guru Gobind Sing Govt. Hospital	Raghubir Nagar , New Delhi-27	Yes	No	Replied that installation of RWHS is under Process
76	Babu Jagjeevan Ram Memorial Hospital	Jahangirpuri, Delhi-33	Yes	No	It is replied that as per PWD & CGWB letter dated 24.09.2010, water level is 5-6 meter ground level. Thus, RWHS may lead water logging.
77	Anand Hospital	B-13, Nirmal Vihar, Najafgarh, New Delhi-43	Yes	No	No reasons given
78	Kalra Hospital	A-5 & 6, Kirti Nagar, New Delhi-15	Yes	No	It is replied that they are not in position of providing RWHS due old building structure.
79	Satyawadi Raja Harish Chander hospital	Plot No.-30, Sector-7A, Narela, Delhi-40	Yes	No	Replied that there is no need of RWHS
80	Guru Nanak Eye Centre	Maharaja Ranjit Singh Marg, New Delhi	Yes	No	It is informed that due to high water level, RWHS not installed.

264

(15)

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd." . (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
81	Jaipur Golden Hospital	2, Institutional Area, Sec-3, Rohini, Delhi-85	Yes	No	It is replied on 05.08.2014 that RWHS can not be installed due to high water level, .
82	St. Stephen's Hospital	Tis Hazari, Delhi-54	Yes	No	Replied that, No necessity for providing RWHS
83	E.S.I. Hospital	Basai Darapur, Ring Road, New Delhi-15	Yes	No	It is replied on 08.09.14 that present hospital buildings are very old & no RWHS was introduced at the time of construction. However, RWHS is proposed in the ongoing new project of Medical College & Hospital
84	Maharishi Valmiki Hospital	Pooth khurd, New Delhi-39	Yes	No	It is replied on 22.07.14 that there is no need of RWHS as rain water is dained into a pond adjacent to the hospital
85	M.V.I.D Hospital	MCD, Kingsway Camp, Delhi-9	Yes	No	It is replied on 25.08.14 that there is no need of RWHS due to high water table.
86	Bhagwan Mahavir Hospital	H-4/5, Pitampura, Delhi - 110034	Yes	No	It is replied that RWHS can not be installed due to High Water Table
87	Ayurvedic Hospital	MCD, Haiderpur, New Delhi-52	No		
88	ESI Hospital	Sri Maa Anand Mayee Marg, Okhla, Phase-1 New Delhi-20	No		
89	Hedgewar Arogya Sansthan	F-18, Karkardooma, Opposite C.P.C.B. Delhi-32	No		
90	Ashok Nursing Home	F-3/15,F-3/16, Krishna nagar Delhi-51	No		
91	Altius Sonia Hospital	1, Gulshan Park, Main Rohtak Road, Nangloi, Delhi-41	No		
92	Shri Ram Singh Memorial Hospital	B-25, 26, East Krishna Nagar, New Delhi-51	No		
93	Indian Hospital	AG-35, Shalimar Bagh, New Delhi-88	No		
94	Charak Palika Hospital	Moti Bagh, New Delhi-21	No		
95	Jag Pravesh Chand Hospital (Shastri Park Hospital)	Govt. of NCT of Delhi, Shastri Park, Delhi-53	No		
96	Mata Chanan Devi Hospital	C-1, Janakpuri, New Delhi-58	No		
97	Park Hospital	11, 12 & 13, Meera Enclave, Chowkandi Near Keshavpur Depot, Outer Ring Road, New Delhi-18	No		

363

13

Status Report of Rainwater Harvesting System in Hospitals w.r.t. orders of Hon'ble NGT dated 05.08.2014 in MA No. 808/2013 in OA No. 94/2013 in the matter of "Vikrant Kumar Tongad Vs DMRC Ltd." . (Annexure-3)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional in Hospital (as per reply)	Remarks
98	E.S.I Hospital	Sector-15, Rohini, Delhi - 85	No		
99	G.B. Pant Hospital	Jawahar Lal Nehru Marg, New Delhi-2	No		
100	Lok Nayak Hospital	Jawaharlal Nehru Marg, New Delhi-2	No		

Status of Rainwater Harvesting System in Hospitals as per inspection done by the Committees (Annexure 4)

S.No.	Name of the Hospital	Address of Hospital	Whether Reply received (Yes or No)	Status of RWHS installed & / functional (as per reply)	Status as per the inspection report of the Committee
1	Saroj Hospital	2, Institutional Area, Sec-14, Madhuban Chowk, Rohini, Delhi-85	Yes	Yes	Two nos. of RWHS installed, found satisfactory
2	Indian Spinal Injuries Centre	Sector-C, Vasant Kunj, New Delhi-70	Yes	Yes	Three nos. of RWHS installed, found satisfactory. One RWHS is under construction.
3	Fortis Lt. Rajan Dhall Charitable Trust	Sector- B, Pocket-1, Aruna Asaf Ali Road, Vasant Kunj, Delhi-70	Yes	Yes	Two nos. of RWHS installed, found satisfactory
4	Dr. Baba Saheb Ambedkar Hospital	Sector-6, Rohini , New Delhi-85	Yes	Yes	Five nos. of RWHS installed, found satisfactory
5	Bhagwati Hospital (A unit of Sarvodaya Health Foundation (Regd.) Delhi)	CS/OCF-6, Sector-13, Rohini, Delhi-85	Yes	Yes	One no. of RWHS installed, found satisfactory

192

Annexure - 5

15

status of Rain Water Harvesting Systems of RWAs, inspected by the Committees constituted w.r.t. Hon'ble National Green Tribunal's Order Dated 04.07.2014 in OA No. 94/2013 "Vikrant Kumar Tongad Vs DMRC Ltd." (Annexure-5)

S.No	Name & Address of the Resident Welfare Association (RWA)	District	Reply Received from	Reply Received on	Brief of Reply	Inspected by	Date of Inspection	Brief of Observations of the Committee
1	Maharani Bagh Co-operative House Building & Welfare Society Ltd., 1 Central Avenue Maharani Bagh, New Delhi-65	South	Sh. Shailendra Haruray Hony. Secretary	03.07.2014	1. It is informed that there are 22 RWHS. 2. 18 are functional & 4 are non functional.	Committee I	24.07.2014	1) Overall condition of Rain Water Harvesting Structures (22 Nos.) is not satisfactory. 2) Not maintained well. 3) 18 functional and 4 non-functional.
2	Mandakini Enclave Resident Welfare Association, (Regd.) Alaknanda New Delhi-19	South	Sh. Shyam Sachdeva, President	04.07.2014	1. Rain Water Harvesting System has been installed since 2009 2. System is functional however to improve the efficiency they are in process of cleaning the rain water wells with the help of MCD and NGO.	Committee I	23.07.2014	1) Overall condition of Rain Water Harvesting Structures (6 Nos.) is satisfactory. 2) Six pits exist without tubewell.
3	Munirka Vihar Welfare Association, 210, Munirka Vihar, New Delhi-67	South West	Col. Shivraj President	21.07.2014	1. Rain Water Harvesting System had been installed a couple of year back but in defunct condition due to encroachment.	Committee I	04.08.2014	1) Overall condition of Rain Water Harvesting Structures (3 Nos.) is not satisfactory. (Poorly maintained) 2) Out of three major structures found one is clogged.
4	Green Park Extension Association (Regd.), G-6 Green Park Extension, New Delhi-16	South	Sh. CK Jain, Hony. Secretary SC Agarwal, President	21.07.2014	1. Eight Rain Water Harvesting System were installed by Delhi Jal Board long back. 2. Most of Rain Water Harvesting System seems to be not functional due to deposit of silt in the chamber.	Committee I	04.08.2014	1) Overall condition of Rain Water Harvesting Structures (9Nos.) satisfactory. 2) 7 Rain Water Harvesting Structures out of 9 are functional. 3) Drains are not clean, all rainwater drain silted up.
5	Resident's Welfare Association, Yusuf Sarai, 51, Mandir Wali Gali, Yusuf Sarai, New Delhi-16	South	Sh. Rakesh Gupta, Secretary	03.07.2014	1. Rain Water Harvesting Systems have been sanctioned by GNCT Delhi for 5 sites. 2. Out of 5 sites the work of 3 sites have been completed, 2 are still pending. 3. The 3 Rain Water Harvesting System which have been completed are not working.	Committee I	22.07.2014	1) Overall condition of Rain Water Harvesting Structures (3 Nos.) is not satisfactory. 2) There are 3 Rain Water Harvesting Structures installed 3) The structures were completely filled with garbage, used as parking area. Nothing is visible as they are filled up. Totally non-functional.
6	Asiad Village Society, Praduman Singh Marg, Asiad Village Complex, New Delhi-49	South	Capt. Sh. Krishan Sharma, Secretary	08.07.2014	1. SMDC has installed and maintaining Water Harvesting System in the complex.	Committee I	22.07.2014	1) Overall condition of Rain Water Harvesting Structures (1 No.) is not satisfactory. 2) Only one Rain Water Harvesting Structures was found, reported that no maintenance has been done in past 3 years. 3) The structure was built by MCD and supposed to be maintained by them. 4) The existing Rain Water Harvesting Structures is not functional and not sufficient.
7	Chattarpur Enclave Residents Welfare Association, C-1 Chattarpur Enclave, Phase-II New Delhi-74.	South	Sh. Rajinder Sejwal, President	02.07.2014	1. Six No. Water Harvesting Recharge Structures were constructed in Feb-2013. 2. None of the structures is functional and lying dumped.	Committee I	23.07.2014	1) Overall condition of Rain Water Harvesting Structures (6 Nos.) is Defunct. 2) Not properly constructed. 3) Structures were built by Flood department. 4) Completely filled up & nothing visible.

status of Rain Water Harvesting Systems of RWAs, inspected by the Committees constituted w.r.t. Hon'ble National Green Tribunal's Order Dated 04.07.2014 in OA No. 94/2013 "Vikrant Kumar Tongad Vs DMRC Ltd." (Annexure-5)

S.No	Name & Address of the Resident Welfare Association (RWA)	District	Reply Received from	Reply Received on	Brief of Reply	Inspected by	Date of Inspection	Brief of Observations of the Committee
8	Anand Niketan Residents Welfare Association (Regd.) D-50 Anand Niketan New Delhi-21	New Delhi	Sh. Virendra Sood, General Secretary	04.07.2014	1. There are 14 Rain water Harvesting Pits. 2. All are functional and regularly maintained.	Committee I	22.07.2014	1) Overall condition of Rain Water Harvesting Structures (14 Nos.) is satisfactory. 2) Resident Welfare Association is advised to clean up the silt found in some RWHS pits. Also advised to block direct surface flow to prevent silt & clay deposition inside the pit to make the RWHS more efficient.
9	DDA Flats, Sec-11, Pkt-3, Dwarka, New Delhi	South West	Sh. O.P Sharma, President	04.07.2014	1. Rain Water Harvesting System has been installed but not functioning properly	Committee I	26.07.2014	1) Overall condition of Rain Water Harvesting Structures (1 No.) is not satisfactory. 2) RWHS Built by DDA. 3) Not functional, defunct because of no maintenance. 4) More structures required to be built to harvest all the water.
10	Delhi Hindustani Mercantile, Co-operative Group Housing Society Ltd., Kalish Apts, Plot-2 Sec-4, Dwarka, New Delhi-78	South west	Sh. A.K.L Das President	21.07.2014	1. There are 2 Rain Water Harvesting Systems installed, and they are functional	Committee I	26.08.2014	1) Overall condition of Rain Water Harvesting Structures (2 Nos.) is satisfactory. 2) Suggested to create opening to the recharge well.
11	Great Capital Cooperative Group Housing Society Ltd. (Reg.) Plot No. 15, Sector-6, Dwarka, New Delhi-75	South West	Ms. Rajni Taneja, President V.P Gupta, Vice President	05.08.2014	1. Rain Water Harvesting Structures has been installed and have been regularly cleaned & maintained.	Committee I	26.08.2014	1) Overall condition of Rain Water Harvesting Structures (2 Nos.) is satisfactory. 2) Filter media needs to be cleaned. 3) Storm water drains also needs cleaning.
12	Resident Welfare Association, Nizamuddin East Colony, New Delhi-13	South	Sh. Rahul Sawhny, President	04.08.2014	1. There are 13 RWH pits, 8 of them are maintained by Welfare Association & 5 by SOMC. 2. All are functioning properly	Committee I	03.09.2014	1) Overall condition of Rain Water Harvesting Structures (13 Nos.) is satisfactory. 2) Earth layer found in all pits should be cleaned 3) Cap broken should be replaced. 4) Pit 3 water logged.
13	Residents Welfare Association, Roop Nagar, Block-2, (Regd.) 2/93 Roop Nagar Delhi-07	North	Sh. Vijay Vinod Sharma, President	03.07.2014	1. A Rain Water Harvesting System has been installed properly in Roop Nagar Block-7 a few months ago and is functional.	Committee II	01.08.2014	1) Overall condition of Rain Water Harvesting Structures (1 No.) is not satisfactory. 2) Need immediate removal of silt and regular maintenance is required.
14	Trinagar Residents Welfare Association, (Regd.) 1736-A/126, Shanti Nagar, Trinagar, Delhi-35	North West	Sh. Pawan Kumar Jain, President	03.07.2014	1. Two Rain Water Harvesting System have been installed & both are working properly.	Committee II	01.08.2014	1) Overall condition of Rain Water Harvesting Structures (No 2) is satisfactory. 2) Needs cleaning of filter medium at least once in a year before monsoon i.e. in April-May every year.

267
17

status of Rain Water Harvesting Systems of RWAs, inspected by the Committees constituted w.r.t. Hon'ble National Green Tribunal's Order Dated 04.07.2014 in OA No. 94/2013 "Vikrant Kumar Tongad Vs DMRC Ltd." (Annexure-5)

S.No	Name & Address of the Resident Welfare Association (RWA)	District	Reply Received from	Reply Received on	Brief of Reply	Inspected by	Date of Inspection	Brief of Observations of the Committee
15	Federation of Welfare Associations, (Regd.) Tagore Garden & Tatarpur BA-336, Tagore Garden, New Delhi-27	West	Sh. K.K.Pathak, Secretary General	08.07.2014	1. One Rain Water Harvesting System has been installed, and its functioning is yet to be tried and tested	Committee III	01.08.2014	1) Overall condition of Rain Water Harvesting Structures (No.1) is not satisfactory. 2) This Rain Water Harvesting System has been constructed by MCD around one & half year back. Charging of RWH system is through storm water drain includes surface water. 3) Proper maintenance & cleaning of filter media should be required. 4) MCD/ Resident Welfare Association should take action to stop surface water charging in RWH system.
16	Navyug Adarsh Co-operative Group Housing Society Ltd., F Block, Vikaspuri, New Delhi-18	West	Sh. Balbir Singh, President	03.07.2014	1. Rain Water Harvesting System have been installed in 2008 and the same is functional and is being maintained & cleaned regularly.	Committee III	23.07.2014	1) Overall condition of Rain Water Harvesting Structures (3 Nos.) is satisfactory. 2) System found in good condition.
17	Federation of Naraina Vihar Resident Welfare Associations B-77, Naraina Vihar, Delhi	New Delhi	Sh. Satya Prakash, President	01.07.2014	1. Three Rain Water Harvesting System have been installed. 2. Out of which two are functional & one is partially functional.	Committee III	01.08.2014	1) Overall condition of Rain Water Harvesting Structures (2 Nos.) is not satisfactory. 2) Cleaning of filter medium required and to be maintained properly. 3) The Rain Water Harvesting System have been constructed through NGO Force about 9 years back. 4) Resident Welfare Association should take action to stop charging from homes & surface water. 5) 3rd Rain Water Harvesting System existed opp. A-59, Naraina Vihar, A-Block and same has been destroyed/damaged by DMRC.
18	Tilak Nagar Welfare and Vigilance Association Regd., 12/46A, Tilak Nagar, New Delhi-18	West	Sh. C.P.Malhotra, President	07.07.2014	1. One Rain Water Harvesting System has been installed in weight and measurement office at Tilak Nagar & functioning satisfactorily.	Committee III	23.07.2014	1) Overall condition of Rain Water Harvesting Structures (1 No.) is not satisfactory. 1) Rain Water Harvesting Structure constructed & operated by PWD. 2) Roof water & ground water is connected with Rain Water Harvesting System. Advised to disconnect ground/surface water. 3) Proper maintenance required.
19	The Friends Central Govt. Employees Co-op. House Bldg. Society Ltd. Adjoining the complex of Prachin Durga Mandir, Surya Niketan, Delhi-92	East	Sh. P.P.Matta, President Dinesh Gupta, Secretary	04.07.2014	1. Rain Water Harvesting System has been installed at Park No.-2, Surya Niketan and in functioning condition.	Committee IV	22.07.2014	1) Society is not at all involved in this job, Rain Water Harvesting System (1 No.) is installed by EDMC in a park. 2) It is catering rain water of park only of area 200 sq mir approx. 3) For its proper use, rain water from road surface/ drains needs to be connected with RWH Structures.

358

TR

Status of Rain Water Harvesting Systems of RWAs, inspected by the Committees constituted w.r.t. Hon'ble National Green Tribunal's Order Dated 04.07.2014 in OA No. 94/2013 "Vikrant Kumar Tongad Vs DMRC Ltd." (Annexure-5)

S.No	Name & Address of the Resident Welfare Association (RWA)	District	Reply Received from	Reply Received on	Brief of Reply	Inspected by	Date of Inspection	Brief of Observations of the Committee
20	Pawitra Co-operative Group Housing Society Ltd., 12, Vasundhara Enclave, Delhi-96	East	Smt. Indra Behl, President	04.07.2014	1. Rain Water Harvesting System has been installed, & it is functional.	Committee IV	22.07.2014	1) There exist 6 Rain Water Harvesting Structures Filter media cleaning & development of bore. 2) Balcony discharge should not be allowed in RWH Structure.
21	Munirka Enclave Residents Association (Regd.), Mera Office, Munirka Enclave, Nelson Mandela Marg, New Delhi- 67	South West	Col (Retd.) H.C.Saroja, President	01.07.2014	1. A small Rain Water Harvesting Systems Covers a part of Colony & it is functional.	Committee I		Inspection is to be conducted by the committee.
22	Pocket K-1 Chittaranjan Park, Residents Welfare Association (Regd.), K-1/30 Chittaranjan Park, Delhi-19.	South	Sh. S.K. Dutta, President	01.07.2014	1. There are 2 Rain Water Harvesting System installed, and both are functional.	Committee I		Inspection is to be conducted by the committee.